Best Practices

By Bruce Stone, Fleet 1

MAINSHEET: If you have the Dawid aluminum plate that splits your coarse tune from your fine tune, it is recommended to disassemble and clean your mainsheet system, as this area is prone to corrosion due to stainless fasteners being attached to aluminum. See pitting in the photos. Good time to replace the Harken fittings as they are under a lot of load and wear out.

